

# Data Sheet

## Digital Thermometer + whisk 2 en 1

Reference 91000-061-ca



## Instructions

1. Take out the battery sleeve.
2. The thermometer is now operational .
3. Hold the " POWER ON/OFF " button for more than 2 seconds to power on/off the thermometer.
4. Use proper tool change unit.
5. Press button shortly will display Max/Min temperature.

## Specifications

- Temperature display : °C/°F
- Range : -30°C+300°C / -22°+572°F
- Accuracy :  $\pm 0,5^{\circ}\text{C}$  /  $\pm 0,9^{\circ}\text{F}$
- Stainless prob : 16cm
- Stainless steel food whisk: removable + dishwasher washable
- Temperature testing period : 1 seconde
- Temperature alert function
- Battery : 1 x Cr2032
- Battery life : more than 4000 hours

Alla France

Z.I. du Bompas - 13, rue du Bompas - Chemillé - 49120 Chemillé-en-Anjou - FRANCE

Tél. + 33 (0)2 41 30 55 08 - Fax +33 (0)2 41 30 34 67

[www.allafrance.com](http://www.allafrance.com)

  
France